



MOTOR WIRING DIAGRAMS FOR THREE PHASE VORTEX COMPRESSORS

LOW VOLTAGE(230V-3PH-60HZ)



INSULATE




LINE 1

LINE 2

LINE 3

HIGH VOLTAGE(460V-3PH-60HZ)



INSULATE

INSULATE

INSULATE

1

2

3

LINE 1

LINE 2

LINE 3

OL435V75B (184015) VX075HC
230V - 2.8 FLA, 3.2 SFA
460V - 1.4 FLA, 1.6 SFA

OL610V100B, (184014), VX100HC
230V - 4.6 SFA
460V - 2.3 SFA

OL1200V200B, (184003) VC200HC
230V - 8.4 SFA
460V - 4.2 SFA